


## STRAINERS

### 192 Y strainer

LOSS DIAGRAM (With water), with a filtration degree of 500 $\mu$ m through 800 $\mu$ m.

192

	1/4"	3/8"	1/2"	3/4"	1"	1"1/4	1"1/2	2"	2"1/2	3"	4"
KV	2,20	3,40	3,80	7,20	11	13	15	28	77	93	146







# STRAINERS

#### LOSS DIAGRAM (With water), with 200µm filtration degree

#### 192A

	1/4"	3/8"	1/2"	3/4"	1"	1"1/4	1"1/2	2"
KV	1,7	2,4	3,5	6,5	8	10	11,5	19,6

