




# STRAINERS

## 193 Nickel-plated Y strainer

### LOSS DIAGRAM (With water), with 500 $\mu$ m filtration degree

193

	1/4"	3/8"	1/2"	3/4"	1"	1 1/4"	1 1/2"	2"
KV	2,20	3,40	3,80	7,20	11	13	15	28






# STRAINERS

## LOSS DIAGRAM (With water), with 300 $\mu$ m filtration degree

193G

	1/4"	3/8"	1/2"	3/4"	1"	1"1/4"	1"1/2"	2"
KV	2,10	3,10	3,50	6,70	9,30	11,00	13,50	18,50





# STRAINERS

## LOSS DIAGRAM (With water), with 50 $\mu$ m filtration degree

### 193GAS

	1/4"	3/8"	1/2"	3/4"	1"	1"1/4"	1"1/2"	2"
KV	1,70	2,60	3,20	5,50	6,80	7,30	7,80	9,80

