

FULL FLOW BALL VALVES: IDEAL

090 Ideal ball valve, full flow

LOSS DIAGRAM (With water)

	1/4"	3/8"	1/2"	3/4"	1"	1"1/4	1"1/2	2"	2"1/2	3"	4"
KV	3,45	5,00	15,65	26,26	41,44	63,69	101	169	348	390	725



