



FULL FLOW BALL VALVES: IDEAL

099 Ideal ball valve, full flow male/male thread

LOSS DIAGRAM (With water)

	1/2"	3/4"	1"	1"1/4	1"1/2	2"
KV	10,05	24,56	51,21	68,65	98,83	177,04

